

Rampion Offshore Wind Farm
Notice To Mariners

Issuer : Rampion Control Room

Date of Issue: 26-05-26

NTM no : NTM RAM-2026-002

For enquiries on this Notice to Mariners please contact:

rampion.controlroom@rwe.com
07816 061 968



To Owners, Ships Agents, Masters, Pilots and Fishermen. Please see the following:

Rampion North & South Special Marks

Rampion wish to advise that maintenance works will be occurring on the North and South marker buoys **04/06/2026 – 05/06/2026.**

WTG	WGS84 Decimal Degrees	
	Latitude	Longitude
North	50° 41' 47.40"N	0° 16' 48.90W
South	50° 38' 33.12"N	0° 16' 56.82"W

General safety information can be found here: <https://www.seafish.org/article/kingfisher-bulletins..> All mariners are requested to make themselves aware of their obligations for conducting activities over buried and protected cables under International and UK Cable (Subsea) Protection Legislation.

Distribution:

As per Rampion Notices To Mariners Distribution List. Please feel free to share the information.

